









Gerber Setup

General Layers Drill Drawing Apertures **Advanced**

Film Size

X (horizontal) 508mm

Y (vertical) 406.4mm

Border size 25.4mm

Leading/Trailing Zeroes

Keep leading and trailing zeroes

Suppress leading zeroes

Suppress trailing zeroes

Aperture Matching Tolerances

Plus 0.0001mm

Minus 0.0001mm

Position on Film

Reference to absolute origin

Reference to relative origin

Center on film

Batch Mode

Separate file per layer

Panelize layers

Plotter Type

Unsorted (raster)

Sorted (vector)

Other

G54 on aperture change

Optimize change location commands

Use software arcs

Generate DRC Rules export file (.RUL)

OK Cancel

