

## Pinout

(roter Punkt) 1	COM	COM	50
2	1E	1G	49
3	1D	1F	48
4	1C	1A	47
5		1B	46
6	2E	2G	45
7	2D	2F	44
8		2A	43
9	2C		42
10		2B	41
11			40
12			39
13	x 10		38
14			37
15			36
16			35
17			34
18			33
19		:	32
20			31
21	-	3G	30
22	3E	3F	29
23	3D	3A	28
24	3C	3B	27
25	COM	COM	26