


2x0.5mm2 red-black

1x0.5mm2 red



Rpm table	
Control signal	RPM value
0V	4800
5V	1800

$$\text{RPM} = 4800 - (\text{control}/5V) * 3000$$