

BOM (sch) C:/Dokumente und Einstellungen/.../iPodCtrl/v02.5.sch um 19.02.2009 17:21:45. Gruppierung aller Bauteile mit gleichem Wert und Gehäuse.

	Qty	Value	Package	Parts
1	10	100nF/50V	C0805_KS	C1, C2, C3, C4, C6, C11, C21, C101, C102, C104
2	1	10uF/25V	153CLV-0505	C5
3	6	1µF/16V	C0805_KS	C7, C9, C10, C12, C13, C14
4	1	10nF/50V	C0603	C8
5	4	1nF/50V	C0603	C15, C18, C19, C20
6	1	47µF/6,3V	153CLV-0505	C17
7	2	1N4007	D-7.5	D1, D4
8	1	BAV70	SOT-23	D3
9	1	MAX232-S	SO16	IC1
10	1	R-78B3.3-1.0	SIP3_RECOM	IC2
11	1	DSC56F8037	LQFP64	IC3
12	1	RE-0505S	NMA	IC6
13	1	R-78B5.0-1.0	SIP3_RECOM	IC7
14	1	Reset	JP1	JP1
15	1	5VEin	JP1	JP2
16	1	G6K-2F-Y	G6K-2F-Y	K1
17	1	CuD Tech. 1410604	INDUCTOR_C_U_D_TECHNOLOGIES_D24.8_H14.2	L1
18	2	BLM21AJ601SN1D	0805	L101, L102
19	4	SE11SE_22_11	SE11	LSP1, LSP2, LSP3, LSP4
20	2	100R	R0805_KS	R1, R2
21	4	22R	0207/2V	R3, R4, R5, R6
22	5	220R	R0805_KS	R7, R18, R24, R100.9, R100.10
23	5	47k	R0805_KS	R8, R74, R100.5, R100.6, R100.7
24	1	270R	R0805_KS	R9
25	2	4k7	R0805_KS	R15, R100.8
26	6	10k	R0805_KS	R16, R73, R75, R76, R77, R78
27	1	2k7	R0805_KS	R17
28	1	330R	R0805_KS	R22
29	1	6k8	R0805_KS	R23
30	1	470k	R0805_KS	R100.1
31	1	27k	R0805_KS	R100.2
32	1	2k2	R0805_KS	R100.3
33	1	68k	R0805_KS	R100.4
34	1	2x7pol	MA07-2	SV1
35	1	2x3pol	MA03-2	SV2
36	1	1x3pol	MA03-1	SV4
37	1	BC848	SOT23	T2
38	9	TPB1,27	B1,27	TP1, TP2, TP3, TP4, TP5, TP6, TP9, TP10, TP11
39	1	1503_09	1503_09_MOD_REICHELT_EBS_35	X1
40	1	DD1B030HA1+NANO4	DD1B030HA1+NANO4	X2
41	1	subd 9pol male	M09HP	X5

Anzahl der Posten: 41