


V	mA
0,1003	0,0000
0,2004	0,0000
0,3002	0,0000
0,3999	0,0000
0,5004	0,0000
0,6000	0,0000
0,7002	0,0000
0,8004	0,0000
0,9003	0,0000
1,0004	0,0000
1,1004	0,0000
1,2020	0,0001
1,3005	0,0001
1,4003	0,0002
1,4998	0,0006
1,6000	0,0036
1,7004	0,0272
1,8000	0,1654
1,9080	0,5447
2,0005	1,0988
2,1005	1,7480
2,1956	2,4354
2,3007	3,1824
2,4006	3,9318
2,4992	4,6863
2,6010	5,4703
2,7006	6,31
2,8005	7,09
2,9022	7,90
2,9967	8,64
3,1009	9,49
3,2007	10,29
3,2994	11,08
3,4009	11,90
3,4992	12,70
3,5998	13,52
3,6994	14,34
3,7998	15,15
3,8986	15,96
3,995	16,78
4,099	17,64
4,199	18,46
4,297	19,27
4,399	20,09
4,498	20,93
4,596	21,75
4,698	22,58
4,795	23,39
4,897	24,24
4,966	25,06



R = 100 Ohm