

mm	TPI	threads per inch	printable	measuring gauge
0.4	63.5		Gewindeschablone zum Ausdrucken	
0.45	56.44		Gewindelinal	Schraubenmessung
0.488	52.0		Gewindelehre für Schrauben	
0.5	50.8		Gewindesteigung feststellen	
0.529	48.0		Umdrehungen pro Zoll	
0.55	46.18		Steigung messen	
0.577	44.0		Gewindeanalyse	
0.6	42.33			
0.635	40.0			
0.7	36.28			
0.706	36.0			
0.75	33.86			
0.794	32.0			
0.8	31.75			
0.847	30.0			
0.907	28.0			
0.977	26.0			
1.0	25.4			
1.058	24.0			
1.155	22.0			
1.2	21.16			
1.25	20.32			
1.27	20.0			
1.337	19.0			
1.411	18.0			
1.5	16.93			
1.587	16.0			
1.693	15.0			
1.75	14.51			
1.814	14.0			
1.954	13.0			
2.0	12.7			
2.116	12.0			
2.25	11.28			
2.309	11.0			
2.4	10.58			
2.5	10.16			
2.54	10.0			
2.75	9.23			
2.822	9.0			
3.0	8.46			

im Druckmenü 100% /
 "Tatsächliche Größe"
 auswählen, sonst
 falscher Maßstab
 <-- mit Lineal überprüfen

<-- check with ruler

<-- or check here