

```
list    p=16f88

include p16f88.inc

;*****
;Programm

    org  0000h

    goto  main

    org  0200h

main    bsf STATUS,RP0

        movlw 0xFF          ;Scheibe Wert in W-Register

        movwf TRISB        ;Bewege das W-Register in das Register1

        bcf STATUS,RP0

        bsf PORTB,4

    end
```