

Netz-verbunden

Laden

Out

Meßverstärker

Scope

LP-ein

+12V

-12V

9,6V



x5-
x2-
x1-

0.0-
1V-
0.2V-

AC
DC
Freq



OK

+

-

V-Pos

H-Pos

sk/Div

Mode

Slope

Level

Ue 1

Ue 2

Ue 3

Ue 4

Ua 1

Ua 2

Ua 3

Ua 4



Ue=100mV/Skt

Ue=1mV/Skt

