



$$R_1 = \frac{U_B - U_F}{I_F}$$

$$R_2 = \frac{(U_{st} - U_{BE}) \cdot \beta \cdot R_1}{U_B}$$

$$U_{BE} \approx 0,6V$$

$$\beta \approx 100$$