






Original  
Microchip TC4427A



Alibaba  
MICREL MIC4427A






polished  
surface



Drain on substrate

Original  
International Rectifier  
IRF7425



Source


Gate

Alibaba  
IVR F7425




Original  
Vishay VS-30BQ015

Alibaba  
30BQ015



**Alibaba**  
SDR0603-1R5ML



Quality problem:  
just 0.5 turn

**Original**  
Bourns SDR0603-1R5ML



No marking of winding start  
Different orientation on tape