


+5V

GND



```
$regfile = "m328pdef.dat"  
$crystal = 1000000  
Config PORTC.5 = Output
```

```
Do  
PORTC.5 = 1  
Waitms 1000  
PORTC.5 = 0  
Waitms 1000  
Loop  
End
```