

Main | Program | Fuses | LockBits | Advanced | HW Settings | HW Info | Auto

Fuse	Value
SELFPRGEN	<input checked="" type="checkbox"/>
DWEN	<input type="checkbox"/>
BODLEVEL	Brown-out detection disabled
RSTDISBL	<input type="checkbox"/>
SPIEN	<input checked="" type="checkbox"/>
EESAVE	<input type="checkbox"/>
WDTON	<input type="checkbox"/>
CKDIV8	<input type="checkbox"/>
SUT_CKSEL	Int. RC Osc. 9.6 MHz; Start-up time: 14 CK + 64 ms

HIGH	0XEF
LOW	0X7A

- Auto read  
 Smart warnings  
 Verify after programming

Program

Verify

Read

Setting mode and device parameters.. OK!

Entering programming mode.. OK!

Reading fuses address 0 to 1.. 0x7A, 0XEF .. OK!

Leaving programming mode.. OK!