



Bauteilfootprints zuweisen

Datei Bearbeiten Einstellungen Hilfe

Footprintfilter:

Footprintbibliotheken	Symbol-Footprint-Zuordnungen	Gefilterte Footprints
01_WI-AEL_SMD.pretty	1 C1 - 100n : 01_WI-AEL_SMD.pretty:C_0306	1 Connector_JAE_WP7B:JAE_WP7B-P034VA1-R8000_2x17-1MP_P0.4mm
Audio_Module	2 C2 - 100n : 01_WI-AEL_SMD.pretty:C_0306	2 Connector_JAE_WP7B:JAE_WP7B-P034VA1-R8000_Longpads_2x17-1M
Battery	3 C3 - 47µ : Capacitor_SMD:C_0805_2012Metric	3 Connector_JAE_WP7B:JAE_WP7B-P040VA1-R8000_2x20-1MP_P0.4mm
Button_Switch_Keyboard	4 C4 - 47µ : Capacitor_SMD:C_0805_2012Metric	4 Connector_JAE_WP7B:JAE_WP7B-P040VA1-R8000_Longpads_2x20-1M
Button_Switch_SMD	5 C5 - 47µ : Capacitor_SMD:C_0805_2012Metric	5 Connector_JAE_WP7B:JAE_WP7B-P050VA1-R8000_2x25-1MP_P0.4mm
Button_Switch_IHT	6 D1 - BAT54J : Diode_SMD:D_SOD-123	6 Connector_JAE_WP7B:JAE_WP7B-P050VA1-R8000_Longpads_2x25-1M
Buzzer_Beeper	7 D2 - BAT54J : Diode_SMD:D_SOD-123	7 Connector_JAE_WP7B:JAE_WP7B-P060VA1-R8000_2x30-1MP_P0.4mm
Calibration_Scale	8 J1 - IN-SMA : Connector_Coaxial:SMA_Amphenol_132134-10_Vertical	8 Connector_JAE_WP7B:JAE_WP7B-P060VA1-R8000_Longpads_2x30-1M
Capacitor_SMD	9 J2 - ~ : TestPoint:TestPoint_Pad_D2.0mm	9 Connector_JAE_WP7B:JAE_WP7B-P070VA1-R8000_2x35-1MP_P0.4mm
Capacitor_Tantalum_SMD	10 J3 - ~ : TestPoint:TestPoint_Pad_D2.0mm	10 Connector_JAE_WP7B:JAE_WP7B-P070VA1-R8000_Longpads_2x35-1M
Capacitor_IHT	11 J4 - OUT-SMA : Connector_Coaxial:SMA_Amphenol_132134-10_Vertical	11 Connector_JAE_WP7B:JAE_WP7B-S034VA1-R8000_2x17-1MP_P0.4mm
Connector	12 Q1 - TAV1-541+ : 01_WI-AEL_SMD.pretty:SOIC-4_TE2769	12 Connector_JAE_WP7B:JAE_WP7B-S034VA1-R8000_Longpads_2x17-1M
Connector_AMASS	13 R1 - 1G : Resistor_SMD:R_1206_3216Metric	13 Connector_JAE_WP7B:JAE_WP7B-S040VA1-R8000_2x20-1MP_P0.4mm
Connector_Amphenol	14 R2 - 1 : Resistor_SMD:R_0805_2012Metric	14 Connector_JAE_WP7B:JAE_WP7B-S040VA1-R8000_Longpads_2x20-1M
Connector_Audio	15 R3 - 62 : Resistor_SMD:R_0805_2012Metric	15 Connector_JAE_WP7B:JAE_WP7B-S050VA1-R8000_2x25-1MP_P0.4mm
Connector_BarrelJack	16 R4 - 62 : Resistor_SMD:R_0805_2012Metric	16 Connector_JAE_WP7B:JAE_WP7B-S050VA1-R8000_Longpads_2x25-1M
Connector_Card	17 R5 - 1 : Resistor_SMD:R_0805_2012Metric	17 Connector_JAE_WP7B:JAE_WP7B-S060VA1-R8000_2x30-1MP_P0.4mm
Connector_Coaxial	18 R6 - 4R7 : Resistor_SMD:R_0805_2012Metric	18 Connector_JAE_WP7B:JAE_WP7B-S060VA1-R8000_Longpads_2x30-1M
Connector_DIN	19 R7 - 1 : Resistor_SMD:R_0805_2012Metric	19 Connector_JAE_WP7B:JAE_WP7B-S070VA1-R8000_2x35-1MP_P0.4mm
Connector_Dsub	20 R8 - 47 : Resistor_SMD:R_0805_2012Metric	20 Connector_JAE_WP7B:JAE_WP7B-S070VA1-R8000_Longpads_2x35-1M
Connector_FFC-FPC		
Connector_Harting		
Connector_Harwin		
Connector_Hirose		
Connector_Hirose_FX8		
Connector_IDC		
Connector_JAE		
Connector_JAE_WP7B		

Gefiltert nach Bibliothek (Connector_JAE_WP7B): 20 passende Footprints

Ort der Bibliothek: E:\Program Files\KiCad\9.0\share\kicad\footprints/Connector_JAE_WP7B.pretty

Übernehmen, Schaltplan speichern & Fortfahren OK Abbrechen